## PRINTED: 02/21/2013 DEPARTMENT OF HEALTH AND HUMAN SERVICES FORM APPROVED CENTERS FOR MEDICARE & MEDICAID SERVICES OMB NO. 0938-0391 (X3) DATE SURVEY STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING B. WING 345234 02/20/2013 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 1555 WILLIS AVENUE **GOLDEN LIVINGCENTER - LUMBERTON** LUMBERTON, NC 28358 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETION (EACH DEFICIENCY MUST BE PRECEDED BY FULL PRÉFIX **PREFIX** (EACH CORRECTIVE ACTION SHOULD BE DATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG CROSS-REFERENCED TO THE APPROPRIATE TAG **DEFICIENCY**) F 000 INITIAL COMMENTS F 000 The facility is in compliance with the requirements of 42 CFR Part 483, Subpart B for Long Term Care Facilities (General Health Survey). Event ID L93511.

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

## DEPARTMENT OF HEALTH AND HUMAN SERVICES PRINTED: 03/11/2013 CENTERS FOR MEDICARE & MEDICAID SERVICES FORM APPROVED OMB NO. 0938-0391 STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING 01 - MAIN BUILDING 01 COMPLETED 345234 B. WING 03/06/2013 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **GOLDEN LIVINGCENTER - LUMBERTON** 1555 WILLIS AVENUE LUMBERTON, NC 28358 (X4) ID PREFIX SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (EACH DEFICIENCY MUST BE PRECEDED BY FULL (X5) COMPLETION DATE PREFIX (EACH CORRECTIVE ACTION SHOULD BE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG CROSS-REFERENCED TO THE APPROPRIATE TAG DEFICIENCY Preparation and or execution of this plan of K 000 INITIAL COMMENTS K 000 correction do not constitute admission or agreement by the provider of the truth of the This Life Safety Code (LSC) survey was facts alleged or conclusion set forth in the conducted as per The Code of Federal Register statement of deficiencies. The plan of at 42 CFR 483.70(a); using the 2000 Existing correction is prepared and or executed solely Health Care section of the LSC and its referenced because the provision of federal and state laws publications. This facility is Type III protected reauires it. construction utilizing North Carolina Special K 025 locking arrangements, and is equipped with an SS=Dautomatic sprinkler system. Criteria 1 CFR#: 42 CFR 483.70 (a) K 025 NFPA 101 LIFE SAFETY CODE STANDARD K 025 Maintenance Director and SS=D 4/20/13 Maintenance Assistant Smoke barriers are constructed to provide at re-educated to ensure no unsealed least a one half hour fire resistance rating in penetrations in rated walls, accordance with 8.3. Smoke barriers may terminate at an atrium wall. Windows are Unsealed penetration corrected. protected by fire-rated glazing or by wired glass panels and steel frames. A minimum of two Criteria 2 separate compartments are provided on each floor. Dampers are not required in duct All other rated walls above bed penetrations of smoke barriers in fully ducted lights inspected to ensure no unsealed heating, ventilating, and air conditioning systems. penetrations in rated walls. 19.3.7.3, 19.3.7.5, 19.1.6.3, 19.1.6.4 Criteria 3 Maintenance Director and/or Maintenance Assistant will monitor This STANDARD is not met as evidenced by: all rated walls weekly to ensure any Based on the observations and staff interviews penetrations in rate walls are on 3/6/2013 the following Life Safety item was corrected immediately. observed as noncompliant, specific findings

ABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

K 052 | NFPA 101 LIFE SAFETY CODE STANDARD

Marrie

rated walls above the bed lights in room 505.

CFR#: 42 CFR 483.70 (a)

include: There were unsealed penetrations in the

(X6) DATE 19

In the last transfer of transfer of the last transf ther safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days ollowing the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 lays following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued

K 052

ORM CMS-2567(02-99) Previous Versions Obsolete

SS=E

Event ID: L93521

Facility ID: 953293

Criteria 4

The information from the weekly

until no longer deemed necessary.

monitoring will be brought to

the QAPI committee monthly

for a minimum of 3 months or

If continuation sheet Page 1 of 3




## DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MED

PRINTED: 03/11/2013 FORM APPROVED OMB NO. 0938-0391

| CENTE   | RS FOR MEDICARE  | & MEDICAID SERVICES   |  |  | FORM   | M APPROVE                  |
|---|--|---|--|--|--|----------------------------|
| STATEMENT OF DEFICIENCIES<br>AND PLAN OF CORRECTION |  | (X1) PROVIDER/SUPPLIER/CLIA<br>IDENTIFICATION NUMBER:   | (X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 |  | OMB NO. 0938-039<br>(X3) DATE SURVEY<br>COMPLETED  |                            |
|   |  | 345234  | B. WING  |  | 03/00/0046   |                            |
|   | PROVIDER OR SUPPLIER   |   |  | STREET ADDRESS, CITY, STATE, ZIP CODE<br>1555 WILLIS AVENUE<br>LUMBERTON, NC 28358   | 1 03   | /06/2013                   |
| (X4) ID<br>PREFIX<br>TAG                            | (EACH DEFICIENCY   | TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)   | ID<br>PREFIX<br>TAG  | PROVIDER'S PLAN OF CORRECTION  | DRE  | (X5)<br>COMPLETION<br>DATE |
|   | A fire alarm system installed, tested, and with NFPA 70 Nation 72. The system has  | required for life safety is<br>I maintained in accordance<br>nal Electrical Code and NFPA<br>an approved maintenance<br>complying with applicable | K 05   | K 052 SS=E  Criteria 1  The Maintenance Director and Maintenance Assistant were reeducated to ensure the sounder for the fire alarm system on 700 Hall sounded properly (not muffled).  Simplex notified and scheduled for visit to assess and correct muffled sounder.  | · company control cont | 4/20/13                    |
| coniir<br>nn a fo<br>p C<br>K 144<br>SS=E G<br>ur   | Based on the observen 3/6/2013 the followed as noncompletude: The alarm best of operating properly ctivation of the fire alor the bell was muffle roper sound for that it FR#: 42 CFR 483.76 | 0 (a) TY CODE STANDARD ted weekly and exercised tes per month in  | K 144  | All other sounders were assessed to ensure operating properly when tested.  Criteria 3  The Maintenance Director and/or Maintenance Assistant will monitor the fire alarm sounders for all hallways weekly to ensure operating properly, i.e. alarm not muffled.  Criteria 4  The results from the weekly monitoring will be brought to the QAPI meeting monthly for a minimum of 3 months and until no longer deemed nece |  |                            |



| CENTI   | R I MENT OF HEALTI<br>ERS FOR MEDICARI   | HAND HUMAN SERVICES  & MEDICAID SERVICES   |  | F   | RINTEI<br>FORI | D: 03/11/201<br>MAPPROVE                   |  |  |
|---|--|--|--|---|----------------|--|--|--|
| AND PLAN OF CORRECTION  |  | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:   | (X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 |   |                | MB NO. 0938-039 (X3) DATE SURVEY COMPLETED |  |  |
|   |  | 345234   | 8. WING  |   | 02/00/0040     |  |  |  |
| NAME OF PROVIDER OR SUPPLIER  GOLDEN LIVINGCENTER - LUMBERTON |  |  |  | STREET ADDRESS, CITY, STATE, ZIP CODE  1555 WILLIS AVENUE  LUMBERTON, NC 28358  |                |  |  |  |
| (X4) ID<br>PREFIX<br>TAG                                      | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)   |  | ID<br>PREFIX<br>TAG  | PROVIDER'S PLAN OF CORRECTION   | DE             | (X5)<br>COMPLETION<br>DATE                 |  |  |
|   | on 3/6/2013 the follow observed as noncom include: The general give a visual indication supplying the load for tested. There was arrangementator was running NOTE: The transfer of | STANDARD is not met as evidenced by: ed on the observations and staff interviews /6/2013 the following Life Safety item was rved as noncompliant, specific findings de: The generator annunciator panel did not a visual indication that the generator was lying the load for the emergency circuit when d. There was an indication that the rator was running.  E: The transfer of the emergency circuit did within the required ten seconds or less. |  | Criteria 1  The Maintenance Director and Maintenance Assistant were educated to ensure the generator annunciator panel gives a visual indication when the generator is supplying the load for the emergency circuit when tested.  Criteria 2  Cummings Atlantic was notified and scheduled for a visit in order to assess and correct the visual indication on the annunicator panel when the generator is supplying the load for the emergency circuit when tested.  No other annunciator panels |                | 4/20/13                                    |  |  |
|   |  |  |  | exist.  Criteria 3  Maintenance Director and/or Maintenance Assistant will monitor the annunciator panel weekly to ensure the visual indication on the annunciator panel is lit when the generator is supplying the load for the emergency circuit when tested.  Criteria 4  The results of the weekly monitoring will be brought to the QAPI committee monthly for a minimum of 3 months and until   |                |  |  |  |





----