## DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/27/2015 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION  A. BUILDING 01 - MAIN BUILDING 01			(X3) DATE SURVEY COMPLETED	
		345163	B. WING			02/11/2015	
NAME OF PROVIDER OR SUPPLIER  GLENBRIDGE HEALTH AND REHABILTATION CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE 211 MILTON BROWN HEIRS ROAD BOONE, NC 28607				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	(EACH CORRECTIVE ACTION S	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		
K 000	INITIAL COMMENTS  A Life Safety Code (LSC) survey was conducted		K	00			
	as per The Code of F	ederal Register at 42CFR 2000 Existing Health Care and its referenced xit conference all					
	Stories: 1 Construction Type V Constructed: 6/22/20 Fully Sprinkled - Yes At time of survey the: Certified Beds: Medi Census - 111	01					
K 025 SS=F	NOT MET as evidend NFPA 101 LIFE SAFE Smoke barriers are co	2 CFR, Subpart 483.70(a) is the by: ETY CODE STANDARD  Constructed to provide at fire resistance rating in	КС	25		3/20/15	
	accordance with 8.3. terminate at an atrium protected by fire-rated panels and steel fram separate compartment floor. Dampers are not penetrations of smokers.	Smoke barriers may n wall. Windows are d glazing or by wired glass les. A minimum of two hts are provided on each of required in duct e barriers in fully ducted nd air conditioning systems.					
	This STANDARD is a 42 CFR 483.70 (a)	not met as evidenced by:					
ABORATORY	DIRECTOR'S OR PROVIDER/S	SUPPLIER REPRESENTATIVE'S SIGNATURE		TITLE		(X6) DATE	

03/09/2015

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

## DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/27/2015 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION  A. BUILDING 01 - MAIN BUILDING 01		(X3) DATE SURVEY COMPLETED	
		345163	B. WING _		02/11/2015	
NAME OF PROVIDER OR SUPPLIER  GLENBRIDGE HEALTH AND REHABILTATION CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 211 MILTON BROWN HEIRS ROAD BOONE, NC 28607		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPR DEFICIENCY)	BE COMPLETION	
K 025	Continued From pa	ge 1	K 0	25		
K 038 SS=D	Continued From page 1  Based on observations, on 2/11/2015 at approximately 8:00 AM onward, the following deficiencies were noted:  1) The two smoke walls in the attic located on the Linn Cove Hall have holes and/or penetrations that were not sealed in order to maintain the fire resistance rating of the wall.  2) The smoke wall in the attic above the kitchen have hole in the wall at a cable penetration that was not sealed in order to maintain the required fire resistance rating of the wall.  NFPA 101, 19.3.7.3  NFPA 101, 8.3.6.1  This deficiency affected 5 of approximately 9 smoke compartments.  Failure to comply with minimum standards as referenced increases the risk of death or injury due to fire and/or smoke.  NFPA 101 LIFE SAFETY CODE STANDARD  Exit access is arranged so that exits are readily accessible at all times in accordance with section 7.1. 19.2.1  This STANDARD is not met as evidenced by: 42 CFR 483.70 (a)  Based on observations, on 2/11/2015 at approximately 8:00 AM onward, the following deficiencies were noted:  1) Staff when questioned about the magnetically		K 0	38	3/20/15	

## DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/27/2015 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01		. ,	(X3) DATE SURVEY COMPLETED	
		345163	B. WING _	· · · · · · · · · · · · · · · · · · ·		02/11/2015	
NAME OF PROVIDER OR SUPPLIER  GLENBRIDGE HEALTH AND REHABILTATION CENTER			•	STREET ADDRESS, CITY, STATE, 211 MILTON BROWN HEIRS RO BOONE, NC 28607	ZIP CODE		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFI) TAG	X (EACH CORRECTIVE CROSS-REFERENCED	IN OF CORRECTION E ACTION SHOULD BE D TO THE APPROPRIATE CIENCY)	(X5) COMPLETION DATE	
K 038	Continued From page 2 located at the nurse station in case of an emergency. NFPA 101: 7.2.1.6 This deficiency affected the entire facilty Failure to comply with minimum standards as referenced increases the risk of death or injury due to fire and/or smoke.		K	038			
K 144 SS=F		•	K	144		3/20/15	
	Based on observation approximately 8:00 A deficiencies were not 1) The Emergency Conot crank and transferemergency power in NFPA 110: 3-4.1 NFPA 99 3-4.1.1.8 This deficiency affect Failure to comply with	M onward, the following led: Senerator when tested did let load from normal to 10 seconds.  The determinant of the entire facility in minimum standards as the risk of death or injury					