DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/31/2016 FORM APPROVED OMB NO. 0938-0391

| NAME OF PROVIDER OR SUPPLIER KENANSVILLE HEALTH & REHABILITATION CENTER BY BEASLEY STREET KENANSVILLE, NO. 28349 SIMMARY STATEMENT OF DEPKIENCES BY PROCEED BY TULL BY PROVIDER THAN DEPKIENT TAG REGULATORY (RLSC (DENTIFY) NG INFORMATION) K 000 INITIAL COMMENTS This Life Safety Code(LSC) survey was conducted as per The Code of Federal Register at 42CFR 483.70(a); using the 2000 Existing Health Care section of the LSC and its referenced publications. This building is Type (V211) construction, one story, with a complete automatic sprinker system and using Delayed egress locking system. In the exit conference all deficiencies noted were discussed and acknowledged with administration. At time of survey the: Total Certified Bed Count 92 Census 71 The deficiencies determined during the survey are as follows: K 018 NFPA 101 LIFE SAFETY CODE STANDARD Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas shall be substantial doors, such as those constructed of 134 in he solid bonded one wood, or capable of resisting fire for at least 20 minutes. Clearance between bottom of door and floor covering is not exceeding 1 inch. Doors in fully sprinklered smoke compartments are only required or cester the pessage of smoke. There is no impediment to the closing of the doors. Hold open devices that release when the door is pushed or pulled are permitted. Door shall be provided with a means suitable for keeping the door closed. Dutch doors meeting 19.3.3.3.6 are permitted. Door frames shall be labeled and made of steel or other materials in compliance with 8.3.2.1. Notifier lackers are prohibited by CMS regulations in all health care facilities. | STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: | (X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 | | | (X3) DATE SURVEY COMPLETED | |
|--|---|--|---|--|---|---|-------------------------------|--|
| CASIDE PRETIX SUMMARY STATEMENT OF DEPICIENCIES FREEDRY PRETIX TAG PRETIX PRE | | 345150 | | B. WING | | | 06/09/2016 | |
| PREFIX TAG REGULATORY OR ISC IDENTIFYING INFORMATION) TAG REGULATORY OR ISC IDENTIFYING INFORMATION | | | | | 209 BEASLEY STREET | CODE | | |
| This Life Safety Code(LSC) survey was conducted as per The Code of Federal Register at 42CFR 483.70(a); using the 2000 Existing Health Care section of the LSC and its referenced publications. This building is Type V(211) construction, one story, with a complete automatic sprinker system and using Delayed egress locking system. In the exit conference all deficiencies noted were discussed and acknowledged with administration. At time of survey the: Total Certified Bed Count 92 Census 71 The deficiencies determined during the survey are as follows: NFPA 101 LIFE SAFETY CODE STANDARD K 018 SS=D Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas shall be substantial doors, such as those constructed of 13/4 lnch solid-bonded core wood, or capable of resisting fire for at least 20 minutes. Clearance between bottom of door and floor covering is not exceeding 1 inch. Doors in fully sprinklered smoke compartments are only required to resist the passage of smoke. There is no impediment to the closing of the doors. Hold open devices that release when the door is pushed or pulled are permitted. Door shall be provided with a means suitable for keeping the door closed. Dutch doors meeting 19.3.6.3.8 are permitted. Door farmes shall be labeled and made of steel or other materials in compliance with 8.2.3.2.1. Roller latches are prohibited by CMS regulations in all health care facilities. | PRÉFIX | (EACH DEFICIENCY MUST BE PRECEDED BY FULL | | PREFIX | ((EACH CORRECTIVE ACT CROSS-REFERENCED TO | (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE | | |
| conducted as per The Code of Federal Register at 42CFR 483.70(a); using the 2000 Existing Health Care section of the LSC and its referenced publications. This building is Type V(211) construction, one story, with a complete automatic sprinkler system and using Delayed egress locking system. In the exit conference all deficiencies noted were discussed and acknowledged with administration. At time of survey the: Total Certified Bed Count 92 Census 71 The deficiencies determined during the survey are as follows: K 018 NFPA 101 LIFE SAFETY CODE STANDARD SS=D Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas shall be substantial doors, such as those constructed of 13/4 inch solid-bonded core wood, or capable of resisting fire for at least 20 minutes. Clearance between bottom of door and floor covering is not exceeding 1 inch. Doors in fully sprinklered smoke compartments are only required to resist the passage of smoke. There is no impediment to the closing of the doors. Hold open devices that release when the door is pushed or pulled are permitted. Doors shall be provided with a means suitable for keeping the door closed. Dutch doors meeting 19.3.6.3.6 are permitted. Door frames shall be labeled and made of steel or other materials in compliance with 8.2.3.2.1. Roller latches are prohibited by CMS regulations in all health care facilities. | K 000 | INITIAL COMMENTS | | KC | 000 | | | |
| LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE TITLE (X6) DATE | SS=D | This Life Safety Code(LSC) survey was conducted as per The Code of Federal Register at 42CFR 483.70(a); using the 2000 Existing Health Care section of the LSC and its referenced publications. This building is Type V(211) construction, one story, with a complete automatic sprinkler system and using Delayed egress locking system. In the exit conference all deficiencies noted were discussed and acknowledged with administration. At time of survey the: Total Certified Bed Count 92 Census 71 The deficiencies determined during the survey are as follows: NFPA 101 LIFE SAFETY CODE STANDARD Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas shall be substantial doors, such as those constructed of 13/4 inch solid-bonded core wood, or capable of resisting fire for at least 20 minutes. Clearance between bottom of door and floor covering is not exceeding 1 inch. Doors in fully sprinklered smoke compartments are only required to resist the passage of smoke. There is no impediment to the closing of the doors. Hold open devices that release when the door is pushed or pulled are permitted. Doors shall be provided with a means suitable for keeping the door closed. Dutch doors meeting 19.3.6.3.6 are permitted. Door frames shall be labeled and made of steel or other materials in compliance with 8.2.3.2.1. Roller latches are prohibited by CMS regulations in all health care facilities. | | K | D18 | | 6/9/16 | |

06/23/2016 **Electronically Signed** Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients . (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days

following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/31/2016 FORM APPROVED OMB NO. 0938-0391

| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: | (X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 | | (X3) DATE SURVEY COMPLETED | | | |
|--|--|---|--|--|-------------------------------|--|--|--|
| | | 345150 | B. WING | | 06/09/2016 | | | |
| NAME OF PROVIDER OR SUPPLIER KENANSVILLE HEALTH & REHABILITATION CENTER | | | | STREET ADDRESS, CITY, STATE, ZIP CODE 209 BEASLEY STREET KENANSVILLE, NC 28349 | | | | |
| (X4) ID PREFIX TAG | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) | | ID PREFIX TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD E CROSS-REFERENCED TO THE APPROPRI DEFICIENCY) | | | | |
| K 018 | | | K 018 | The Maintenance Director immediatel repaired the latch as needed in order to operate properly and reliably on June 2016. The Maintenance Director surveyed the remainder of the facility to check all corridor doors for close and positive late on June 9, 2016. Any needed repairs were made upon discovery. The Maintenance Director will continue with weekly door checks for the next for weeks then continue with monthly che ongoing. A summary of all findings and their resewill be presented and discussed during the facility Quality Assurance and Performance Improvement Committee Meeting for the next three month with continued review quarterly thereafter unext annual survey. | ely to 9, he atch | | | |
| K 067 SS=E | Heating, ventilating, a with the provisions of in accordance with th specifications. 19.5 19.5.2.2 This STANDARD is r 42 CFR 483.70 (a) Based on observation approximately 9:00 A | 5.2.1, 9.2, NFPA 90A, not met as evidenced by: | K 06 | - | 6/9/16 y | | | |

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/31/2016 FORM APPROVED OMB NO. 0938-0391

| STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION | | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: | I ` ′ | (X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 | | (X3) DATE SURVEY COMPLETED | | | |
|---|---|--|---|---|--|---|----------|--|--|
| | | 345150 | B. WING _ | B. WING | | | /09/2016 | | |
| NAME OF P | ROVIDER OR SUPPLIER | | | , | STREET ADDRESS, CITY, STATE, ZIP CODE | , | | | |
| KENANS | /ILLE HEALTH & REHA | BILITATION CENTER | | | 209 BEASLEY STREET | | | | |
| | | | | | KENANSVILLE, NC 28349 | | | | |
| (X4) ID PREFIX TAG | SUMMARY S (EACH DEFICIEN REGULATORY OF | ID PREFIX TAG | × | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD E CROSS-REFERENCED TO THE APPROPRI DEFICIENCY) | | (X5) COMPLETION DATE | | | |
| K 067 | Continued From pag | Continued From page 2 | | 067 | , | | | | |
| | non-compliant, specific findings include: The smoke damper located in attic on 300 hall did not | | | The HVAC contractor surveyed the | | | | | |
| | open back up when | fire alarm system was reset. | | remainder of the facility on June 9, 2 | | 16. | | | |
| | · - | | remainder of the facility on June 9, The Maintenance Director will surv remainder of facility to locate and of weekly tests of all dampers for the four weeks to ensure reliable opera and then continue with monthly test during fire drills. A summary of all findings and their will be presented and discussed during the Quality Assurance and Perform Improvement Committee Meeting finext three months, with continued | | A summary of all findings and their reswill be presented and discussed during the Quality Assurance and Performance Improvement Committee Meeting for the next three months, with continued reviquarterly thereafter until next annual | ey the conduct mext cion, ss results cing cance or the eviews | | | |
| | | | | | | | | | |