PRINTED: 04/21/2017 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	1 ' '	PLE CONSTRUCTION G 03 - 0303 - REPLACEMENT BLDG	(X3) DATE SURVEY COMPLETED	
		345090	B. WING		08/29/2016	
NAME OF PROVIDER OR SUPPLIER  WESTCHESTER MANOR AT PROVIDENCE PLACE				STREET ADDRESS, CITY, STATE, ZIP CODE  1795 WESTCHESTER DRIVE  HIGH POINT, NC 27262		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	DATE	
K 000	00 INITIAL COMMENTS		K 00	00		
K 038 SS=D	as per The Code of F 483.70(a); using the 3 section of the LSC ar publications. The faci systems. In the exit onoted were discussed administration.  Stories: Two Construction Type: Il Constructed: 2003 Fully Sprinkled - Yes At time of survey the: Total Certified Bed Cocensus = 123  The requirement at 4 NOT MET as evidence NFPA 101 LIFE SAFI Exit access is arranguaccessible at all times 7.1. 19.2.1  This STANDARD is 142 CFR 482.41(a)  Based on the observation 8/29/2016 at apport the following deficien The facility inspection systems non-compliant The required exit at the dining room has a doinstalled at the vicinity release the doors in a section of the secti	lity is utilizing speical locking conference all deficiencies d and acknowledged with  (211)  2 CFR, Subpart 483.70(a) is the by: ETY CODE STANDARD  ed so that exits are readily in accordance with section and met as evidenced by:  ations, and staff interviews eximately 10:00 AM onward,	K 0:	Preparation and/or execution of this Pl of Correction does not constitute an admission or agreement by the provide the truth of the facts alleged or conclusions set forth on the Statement Deficiencies. This Plan of Correction is prepared and/or executed solely becau required by the provisions of Health and Safety Code Section 1280 and 42 C.F. 405.1907  K-038	of se	

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE (X6) DATE

Electronically Signed 09/08/2016

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

NAME OF PROVIDER OR SUPPLIER  WESTCHESTER MANOR AT PROVIDENCE PLACE  SUMMARY STATEMENT OF DEFICIENCIES  RECHOLORISM CONTROL OF THE MINISTER OF THE MINI	STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION  (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION  A. BUILDING 03 - 0303 - REPLACEMENT BLDG				(X3) DATE SURVEY COMPLETED	
The West Chester Nanor at Providence   1795 West Chester Rive   1795			345090	B. WING _			08/	29/2016
FREETIX TAG   REGULATORY OR LSC IDENTIFYING INFORMATION   TAG   REGULATORY OR LSC IDENTIFYING INFORMATION   TAG					1795 WESTCHESTER DRIVE			
mechanism at this location did not have the ability to be turned back on my manual means when the emergency is cleared. Other such doors in the facility had a similar button for the staff ease of exiting along with a simple switch in the vicinity of the door. The door in question is missing the simple switch.  Ref. 2000 NFPA 101 Section 19.2.1; 7.2.1.6  This deficiency affected one of approxamately eight smoke zones in the facility. Failure to comply with minimum standards as referenced increases the risk of death or injury due to fire and/or smoke  1. Corrective action will be accomplished for those residents found to have been affected by the deficient practice:  A simple switch door release mechanism was installed on the required exit at the double doors of the main dining room on 9/01/16.  Corrective action will be accomplished for those residents having potential to be affected by the same deficient practice:  The Maintenance Director on 9/01/16 completed an audit of all other such facility doors to ensure that the simple switch was functioning properly. Repairs were made as necessary.  3. Measures will be put into place or systemic changes made to ensure that the deficient practice will not occur:  The Maintenance Director or designee will complete a quarterly inspection of all such facility doors to ensure they have the appropriate simple switch and that it is functioning properly. Repairs will be completed as necessary.  4. Indicate how the facility will monitor its performance:  Results will be presented to Quality Assurance team for recommendations	PRÉFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL		PREFI		(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE		COMPLETION
K 052 NFPA 101 LIFE SAFETY CODE STANDARD K 052 9/1/16		mechanism at this look to be turned back on a emergency is cleared facility had a similar at exiting along with a set the door. The door in simple switch.  Ref: 2000 NFPA 101  This deficiency affected eight smoke zones in Failure to comply with referenced increases due to fire and/or smooth	eation did not have the ability my manual means when the . Other such doors in the button for the staff ease of simple switch in the vicinity of question is missing the . Section 19.2.1; 7.2.1.6 ed one of approxamately the facility. In minimum standards as the risk of death or injury oke			1. Corrective action will be accomplish for those residents found to have been affected by the deficient practice:  A simple switch door release mechanis was installed on the required exit at the double doors of the main dining room of 9/01/16.  2. Corrective action will be accomplish for those residents having potential to laffected by the same deficient practice.  The Maintenance Director on 9/01/16 completed an audit of all other such facility doors to ensure that the simple switch was functioning properly. Repawere made as necessary.  3. Measures will be put into place or systemic changes made to ensure that the deficient practice will not occur:  The Maintenance Director or designee complete a quarterly inspection of all s facility doors to ensure they have the appropriate simple switch and that it is functioning properly. Repairs will be completed as necessary.  4. Indicate how the facility will monitor performance:  Results will be presented to Quality Assurance team for recommendations and follow up for 6 months.	ed be : irs	9/1/16

PRINTED: 04/21/2017 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY IDENTIFICATION NUMBER-AND PLAN OF CORRECTION COMPLETED A. BUILDING 03 - 0303 - REPLACEMENT BLDG 345090 B. WING 08/29/2016 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 1795 WESTCHESTER DRIVE WESTCHESTER MANOR AT PROVIDENCE PLACE HIGH POINT, NC 27262 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETION (X4) ID IΠ (EACH DEFICIENCY MUST BE PRECEDED BY FULL **PREFIX** (EACH CORRECTIVE ACTION SHOULD BE PREFIX DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) K 052 Continued From page 2 K 052 SS=E A fire alarm system required for life safety shall be, tested, and maintained in accordance with NFPA 70 National Electric Code and NFPA 72 National Fire Alarm Code and records kept readily available. The system shall have an approved maintenance and testing program complying with applicable requirement of NFPA 70 and 72. 9.6.1.4, 9.6.1.7, This STANDARD is not met as evidenced by: 42 CFR 482.41(a) Preparation and/or execution of this Plan of Correction does not constitute an Based on the facility documentation review on admission or agreement by the provider of the truth of the facts alleged or 8/29/2016 at approximately 10:00 AM onward, the following deficiencies were noted: conclusions set forth on the Statement of The facility inspection of the Fire Alarm Control Deficiencies. This Plan of Correction is Panel components was non-compliant the prepared and/or executed solely because specific items include: required by the provisions of Health and The review of the smoke sensitivity test Safety Code Section 1280 and 42 C.F.R. documentation noted that the last smoke 405.1907 sensitivity test date was June 18th 2014. The smoke sensitivity test must be conducted at a K-052 minimum every other calendar year. Ref: 2000 NFPA 101 Section 19.3.4; NFPA 72, Section 10.4.3.2.2 1. Corrective action will be accomplished for those residents found to have been This deficiency affected the entire facility. affected by the deficient practice: Failure to comply with minimum standards as referenced increases the risk of death or injury The required smoke sensitivity test was conducted on 9/01/16. due to fire and/or smoke 2. Corrective action will be accomplished for those residents having potential to be affected by the same deficient practice: The Maintenance Director on 9/01/16 communicated with the contracted provider who inspects the fire alarm control panel of the need to schedule the

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 03 - 0303 - REPLACEMENT BLDG		(X3) DATE SURVEY COMPLETED			
		345090	B. WING			08/	/29/2016	
NAME OF PROVIDER OR SUPPLIER  WESTCHESTER MANOR AT PROVIDENCE PLACE				STREET ADDRESS, CITY, STATE, ZIP CODE  1795 WESTCHESTER DRIVE  HIGH POINT, NC 27262				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)		(X5) COMPLETION DATE	
K 052 K 061 SS=E	1 NFPA 101 LIFE SAFETY CODE STANDARD			0052	smoke sensitivity test at a minimum of every other year. Inspection provider womplete next smoke sensitivity test by 9/01/18.  3. Measures will be put into place or systemic changes made to ensure that the deficient practice will not occur:  The Maintenance Director or designee schedule the smoke sensitivity test for minimum of every other year with the inspection provider. Adjustments to schedule will be made as necessary to ensure smoke sensitivity test is conduct a minimum of every other year.  4. Indicate how the facility will monitor performance:  Results will be presented to Quality Assurance team for recommendations and follow up for 6 months.	will a ted	9/1/16	
					Preparation and/or execution of this Pl of Correction does not constitute an admission or agreement by the provide the truth of the facts alleged or conclusions set forth on the Statement	r of		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	1 ' '		TIPLE CONSTRUCTION ING 03 - 0303 - REPLACEMENT BLDG		(X3) DATE SURVEY COMPLETED	
		345090	B. WING			08/	29/2016	
NAME OF PROVIDER OR SUPPLIER  WESTCHESTER MANOR AT PROVIDENCE PLACE				STREET ADDRESS, CITY, STATE, ZIP CODE 1795 WESTCHESTER DRIVE HIGH POINT, NC 27262		•		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRI. DEFICIENCY)		(X5) COMPLETION DATE	
K 061	sprinkler system was findings include: The supervisory sign supervised tamper a valve at the Fire Alar could be silenced pe was in the closed po room. Supervisory si permanently except the valve to the norm  Ref: 2000 NFPA 101  This deficiency affec Failure to comply with	ance and inspection of the sonon-compliant, specific all for the electronically larm on the sprinkler control m Control Panel (FACP) rmanently when the valve sition in the sprinkler riser gnals shall not be silenced by reopening/restoration of hal operating position.  Section 19.7.6; 9.7.2.1  ted the entire facility. h minimum standards as a the risk of death or injury	K	061	Deficiencies. This Plan of Correction is prepared and/or executed solely because required by the provisions of Health ar Safety Code Section 1280 and 42 C.F. 405.1907  K-061  1. Corrective action will be accomplish for those residents found to have been affected by the deficient practice:  The supervisory signal for the electronically supervised tamper alarm the sprinkler control valve at the fire also control panel was adjusted by the installation of an alarm module so that could not be silenced on 9/01/16.  2. Corrective action will be accomplish for those residents having potential to affected by the same deficient practice. The Maintenance Director or designee completed a test of the fire alarm pane 9/01/16 to ensure that the supervisory signal for the electronically supervised tamper alarm on the sprinkler control valve at the fire alarm control panel conto be silenced. Adjustments or repair were made as necessary.  3. Measures will be put into place or systemic changes made to ensure that the deficient practice will not occur:  The Maintenance Director or designee	use id id iR.  on arm it hed be :		

STATEMENT OF DEFICIENCIES (X1) AND PLAN OF CORRECTION		IDENTIFICATION NUMBER:		IPLE CONSTRUCTION  IG 03 - 0303 - REPLACEMENT BLDG	COMPLETED			
		345090	B. WING _			08/29/2016		
NAME OF PROVIDER OR SUPPLIER  WESTCHESTER MANOR AT PROVIDENCE PLACE				STREET ADDRESS, CITY, STATE, ZIP CODE  1795 WESTCHESTER DRIVE  HIGH POINT, NC 27262				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			PROVIDER'S PLAN OF (EACH CORRECTIVE AC' CROSS-REFERENCED TO DEFICIENT	TION SHOULD BE THE APPROPRIA			
K 061	Continued From page	ge 5	KO	complete monthly tests for the fire alarm control pane supervisory signal for the supervised tamper alarm control valve at the fire alar panel cannot be silenced a results. The fire alarm conthen be tested annually to supervisory tamper alarm silenced. Adjustments or fire alarm control panel will as necessary.  4. Indicate how the facility performance:  Results will be presented the Assurance team for recommand follow up for 6 months.	I to ensure the electronically on the sprinkle or control and record the atrol panel will ensure the cannot be repairs to the I be completed will monitor in a Quality mendations	e er e I		