## State Form: Revisit Report

Provider / Supplier / CLIA / Identification Number 110748

(Y2) Multiple Construction A. Building B. Wing

(Y3) Date of Revisit 8/13/2013

Name of Facility

THE BAKER CLINIC FOR WOMEN

Street Address, City, State, Zip Code

400-B CRUTCHFIELD ST DURHAM, NC 27704

This report is completed by a State surveyor to show those deficiencies previously reported that have been corrected and the date such corrective action was accomplished. Each deficiency should be fully identified using either the regulation or LSC provision number and the identification prefix code previously shown on the State Survey Report (prefix codes shown to the left of each requirement on the survey report form).

(Y4) Item		(Y5) Date	(Y4) Item		(Y5) Date	(Y4) Item	(Y5)	Date
ID Prefix Reg. #	.0302	Correction Completed 08/06/2013	ID Prefix Reg. #	.0309(C)	Correction Completed 08/06/2013	ID Prefix Reg. #	.0309(D)	Correction Completed 08/06/2013
LSC			LSC			LSC		
ID Prefix Reg. #		Correction Completed	ID Prefix Reg. # LSC		Correction Completed	ID Prefix		Correction Completed
ID Prefix Reg. # LSC			ID Prefix Reg. # LSC			ID Prefix Reg. # LSC		
ID Prefix Reg. # LSC			ID Prefix Reg. # LSC		<del></del>	ID Prefix Reg. # LSC		
ID Prefix Reg. # LSC			ID Prefix Reg. # LSC			Reg. #		
Reviewed E			Date: Signature of Surveyor:		Boone	Dat	te: 08/13/201	
Reviewed E			Date:	Signature of Surveyor:			Dat	
Followup to Survey Completed on: 7/2/2013			Check for any Uncorrected Deficiencies. Was a Summary of Uncorrected Deficiencies (CMS-2567) Sent to the Facility? YES NO					