

1 10A NCAC 14D .0213 is proposed for adoption as follows:

2
3 **10A NCAC 14D .0213 OUTSIDE ENTRANCE AND EXITS**

4 (a) An adult day care program offering overnight respite care services shall have at least two exits on all floor
5 levels. If there are only two, the exit or exit access doors shall be so located and constructed to minimize the
6 possibility that both may be blocked by any one fire or other emergency condition.

7 (b) At least one entrance and one exit door shall have a minimum width of three feet and another shall be a
8 minimum width of two feet and eight inches.

9 (c) At least one principal outside entrance and exit for the residents' use shall be at grade level or accessible by ramp
10 with a one inch rise for each 12 inches of length of the ramp. For the purposes of this Rule, a principal outside
11 entrance and exit is one that is most often used by residents for vehicular access. If the program serves any resident
12 that must have physical assistance with evacuation, the building shall have two outside entrances and exits at grade
13 level or accessible by a ramp.

14 (d) All exit door locks shall be easily operable, by a single hand motion, from the inside all times without keys.
15 Existing deadbolts or turn buttons on the inside of exit doors shall be removed or disabled.

16 (e) All entrances and exits shall be free of all obstructions or impediments to allow for full instant use in case of fire
17 or other emergency.

18 (f) All steps, porches, stoops and ramps shall be provided with handrails and guardrails.

19 (g) In adult day care programs offering overnight respite care services with at least one resident who is determined
20 by a physician or is otherwise known to be disoriented or a wanderer, each exit door for resident use shall be
21 equipped with a sounding device that is activated when the door is opened. The sound shall be of sufficient volume
22 that it can be heard by staff. If a central system of remote sounding devices is provided, the control panel for the
23 system shall be located in the office area or in a location accessible only to staff authorized by the administrator to
24 operate the control panel.

25
26 *History Note: Authority S.L. 2011-104;*

27 *Temporary Adoption Eff. January 1, 2012;*

28 *Eff. October 1, 2012.*

29