DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 12/16/2011 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING			(X3) DATE SURVEY COMPLETED	
		345006	B. Wii		***************************************	C 12/15/2011	
	ROVIDER OR SUPPLIER	SING & REHAB CENTER		37	EET ADDRESS, CITY, STATE, ZIP CODE 724 WIRELESS DRIVE REENSBORO, NC 27455		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG		PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SH CROSS-REFERENCED TO THE APF DEFICIENCY)	ACTION SHOULD BE TO THE APPROPRIATE	
F 000	Long Term Care Fa Survey). No deficiencies we		F	0000			
LABORATORY	Y DIRECTOR'S OR PROVI	DER/SUPPLIER REPRESENTATIVE'S SIG	NATURE		TITLE	*****	(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Facility ID: 922978

DEPARTMENT OF HEALTH AND HUMAN SERVICES FORM APPROVED OMB NO. 0938-0391 CENTERS FOR MEDICARE & MEDICAID SERVICES (X3) DATE SURVEY COMPLETED (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTIONAN STATEMENT OF DEFICIENCIES **IDENTIFICATION NUMBER:** AND PLAN OF CORRECTION A. BUILDING 01 MAIN BUILDING 01 ESPECIAL ABUSES B. WING 345006 01/04/2012 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 3724 WIRELESS DRIVE **BLUMENTHAL JEWISH NURSING & REHAB CENTER** GREENSBORO, NC 27455 PROVIDER'S PLAN OF CORRECTION (X5) COMPLETION SUMMARY STATEMENT OF DEFICIENCIES ID. (X4) ID (EACH CORRECTIVE ACTION SHOULD BE (EACH DEFICIENCY MUST BE PRECEDED BY FULL **PREFIX** PREFIX DATE CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) NFPA 101 LIFE SAFETY CODE STANDARD K 144 K 144 SS=D Generators are inspected weekly and exercised under toad for 30 minutes per month in accordance with NFPA 99. 3.4.4.1. Submission of the response to the Statement of Deficiencies by the undersigned does not constitute as admission that This STANDARD is not met as evidenced by: deficiencies existed, were 42 CFR 483.70(a) correctly cited, and/or require By observation on 1/4/12 at approximately noon correction. the following operational inspection and testing was non-compliant. Specific findings include: documentation for monthly load test was conducted without recording percent rated load or : temperature rise. A load bank test had not been completed within the past year. K 144 Generator Contractor was contacted NFPA 99 3-4.4.2 Record keeping. A written and bids were obtained on 1/10/12. record of inspection, performance, exercising period, and repairs shall be regularly maintained Annual generator load test was and available for inspection by the authority completed on 1/16/12, 1/16/12 having jurisdiction. Documentation of completed NFPA 110 6-4.2 (1999 edition) generator sets in Generator load test is enclosed. Level 1 and Level 2 service shall be exercised at least once monthly, for a minimum of 30 minutes, using one of the following methods: (a) Under operating temperature conditions or at not less than 30 percent of the EPS nameplate (b) Loading that maintains the minimum exhaust gas temperatures as recommended by the (X6) DATE TITLE LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER/REPRESENTATIVE'S SIGNATURE A. PMIN)ISTGATOR

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See Instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Facility ID: 922978

PRINTED: 01/10/2012

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 01/10/2012 FORM APPROVED OMB NO. 0938-0391

AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING 01 - MAIN BUILDING 01 B. WING	SURVEY	
NAME OF PROVIDER OR SUPPLIER BLUMENTHAL JEWISH NURSING & REHAB CENTER STREET ADDRESS, CITY, STATE, ZIP CODE 3724 WIRELESS DRIVE GREENSBORO, NC 27455 ID PROVIDER'S PLAN OF CORRECTION (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG REGULATORY OR LSC IDENTIFYING INFORMATION) K 144 Continued From page 1 manufacturer. NFPA 110 6-4.2.2 (1999 edition) Diesel-powered EPS installations that do not meet the requirements of 6-4.2 shall be exercised monthly with the available EPPS load and exercised annually with supplemental loads at 25 percent of nameplate rating for 30 minutes, followed by 50 percent of nameplate rating for 30 minutes, followed by 75 percent of nameplate rating for 60 minutes, for a total of 2 continuous	(X3) DATE SURVEY COMPLETED	
NAME OF PROVIDER OR SUPPLIER BLUMENTHAL JEWISH NURSING & REHAB CENTER X4) ID SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) PREFIX TAG	04/2012	
REGULATORY OR LSC IDENTIFYING INFORMATION) K 144 Continued From page 1 manufacturer. NFPA 110 6-4.2.2 (1999 edition) Diesel-powered EPS installations that do not meet the requirements of 6-4.2 shall be exercised monthly with the available EPPS load and exercised annually with supplemental loads at 25 percent of nameplate rating for 30 minutes, followed by 50 percent of nameplate rating for 30 minutes, followed by 75 percent of nameplate rating for a total of 2 continuous REGULATORY OR LSC IDENTIFYING INFORMATION TAG CROSS-REFERENCED TO THE APPROPRIATE C		
MFPA 110 6-4.2.2 (1999 edition) Diesel-powered EPS installations that do not meet the requirements of 6-4.2 shall be exercised monthly with the available EPPS load and exercised annually with supplemental loads at 25 percent of nameplate rating for 30 minutes, followed by 50 percent of nameplate rating for 30 minutes, followed by 75 percent of nameplate rating for 60 minutes, for a total of 2 continuous	COMPLETIC DATE	